

working for a safer tommorow KARANDIKAR LABORATORIES PVT. LTD. BOISAR

Format: F#07 b.1 Rev 10

# TYPE TEST REPORT

#### IEC 60529:2013

**Degrees of Protection Provided by Enclosures (IP Code)** 

Report No. .....: : KLPL/BTG/20/12-102

ULR No. ..... TC63112000000569F

Discipline .....: Electrical Discipline

Group/Category ..... Environmental Test Facility

Sub-category ...... Ingress protection test

Date of issue.....: : 21.01.2021

No. of pages .....: : 09 PAGES + Annexure

Compiled by (+ signature).....: Bhavesh Rawate

**Designation: Testing Engineer** 

Approved by (+ signature).....: Ajit Karandikar 4. U. Koscoolikee

Designation: CEO

Item Received On .....: : 28.12.2020 in Good Condition

Test Completion Date .....: : 05.01.2021

Client

Name .....: M/s. Rotork Controls (India) Limited

: 28 B, Ambattur Industrial estate (North),

Ambattur, Chennai-600098.

**Test Specification** 

Standard .....: IEC 60529:2013

Specified IP-Code .....: IP68

**Equipment Under Test** 

Type of Test Object .....: Centork Q650 3 Phase

Model No. .....: Q650

Sr. No.....: 1C63491502

Manufacturer .....: M/s. Rotork Controls (India) Limited

Annexure:

Drawing No...... BR/MISC-11263/01, Rev.No.00, Dated:07.01.2021, (01 Page)

NOTE: 1) This refers only to the particular item(s) submitted for testing.

2) If necessary, this report shall be reproduced ONLY in full.

Head Office: B-101, Ansa Industrial Estate, Saki Vihar Road, Saki Naka, Andheri (E) Mumbai-400072 INDIA Ph: (022) 28471395 Laboratory: Gat#142, Betegaon, Boisar Chilhar Road, Opp. Union Park, Boisar (E) Tal-Palghar, Dist-Palghar-401501, INDIA Phone (02525) 284881/931



Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021

D !  -   -	A	verdicts:
Possible	test case	e verdicts.

Test case does not apply to the test object ......: N ( Not Applicable)

Test object does meet the requirement.....: P ( Pass)

Test item does not meet the requirement .....: : F (Fail)

Test case has not been checked .....: :\_\_\_\_\_\_:

#### General remarks:

"(See remark #)" refers to a remark appended to the report.

"(See appended table)" refers to a table appended to the report.

Throughout this report a point is used as the decimal separator.

The test results presented in this report relate only to the object tested.

This test report shall not be reproduced except in full without the written approval of the testing

Laboratory.

IP6X test conducted at Laboratory (Boisar).

IPX8 test conducted at Laboratory (Boisar).

#### Note: - MAJOR EQUIPMENTS USED

Tests	Required Instruments	ld. No.	Cal Due Date	Used Y/N
1X	Accessibility probe 50 mm Dia.	K&A 405/1A	20.03.2021	N_
2X	Accessibility Probe 12.5 mm Dia.	K&A 405 / 3B	20.03.2021	N
3X	Accessibility Probe 2.5mm Dia.	K&A 405 / 5A	20.03.2021	N
4X	Accessibility Probe 1mm Dia.	K&A 405 / 6B	20.03.2021	Υ
5X / 6X	Vacuum Meter	K&A 1108/1-17	08.02.2021	Y
100 m • 1200000	Rotameter 1.2 LPM	K&A 1135-18	10.07.2021	Υ
	DTC with sensor	K&A 581/2-12	08.05.2021	Υ
	Timer	K&A 581/1-12	16.05.2021	Υ
Х3	Stop Watch	K&A 126-08	09.06.2021	N .
	Pressure Gauge	K&A 383/1	01.01.2021	N
X4	Stop Watch	K&A 126-08	09.06.2021	N
	Pressure Gauge	K&A 384/1	01.01.2021	N
X5	Nozzle 6.3 mm dia.	K&A 381	07.10.2021	N
,,_	Rotameter	K&A 419/2	02.01.2021	N
	Stop Watch	K&A 1.26-08	09.06.2021	N
X6	Nozzle 12.5 mm dia.	K&A 382	07.10.2021	N
7.0	Rotameter	K&A 1102-17	22.05.2021	Υ
	Stop Watch	K&A 126-08	09.06.2021	N
X7 /X8	Scale	K&A 107	07.07.2021	Y
λ, γλο	Stop watch	K&A 126-08	09.06.2021	Y



Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021

	IEC 60529:2013		
Clause	Requirement - Test	Result- Remark	Verdic
10	Marking.		N
11	General requirement for tests.		
11.1	Tests should be carried out under the standard atmospheric		P
	conditions described in IEC 60068-1		
11.2	Test samples shall be in a clean and new condition.		Р
	The relevant product standard shall specify details such as: The		N
	number of samples to be tested;		
	-conditions for mounting, assembling and positioning of the		P
	samples;		
	-the pre-conditioning, if any, which is to be used;		N
	-whether to be tested energized or not;		N
	-whether to be tested with its parts in motion or not;		N
11.5	Empty enclosures		
	If the enclosure is tested without equipment		N
	inside, the manufacturer shall ensure that		
	after the electrical equipment is enclosed		
	the enclosure meets the declared degree of		
	Protection of the final product.		

12	Tests for protection against access to hazardous parts indicated by the first				
	characteristic numeral.				NI.
First,	Test means (Access probes)	Test	Test		N
characteristic	2	force	Conditions		
Numeral.			Refer IEC		
			60529:2013		
0	No test required	-	-		N
1	The access probe, sphere of 50 mm Ø	56N	Cls.12.2		N
_	shall not fully penetrate and adequate	±10%			
	clearance shall be kept.				
2	The jointed test finger may penetrate up	30N	Cls.12.2		Ν
	to 80 mm length but adequate	±10%			
	clearance shall be kept.				
3	The access probe, sphere of 2.5 mm Ø	3N±	Cls.12.2		Ν
	shall not penetrate and adequate	10%			
	clearance shall be kept.				
4	The access probe of 1,0	1N±	Cls.12.2		Ν
	mm Ø shall not penetrate and	10%			
	adequate clearance shall be kept.				
5	Test conditions for IP 5X: Same As	1N±	Cls.12.2		Ν
	Above	10%			
6	Test conditions for IP 6X: Same As	1N±	Cls.12.2	Test wire does	Р
	Above	10%		not penetrate	
				inside the UUT.	1

Head Office: B-101, Ansa Industrial Estate, Saki Vihar Road, Saki Naka, Andheri (E) Mumbai-400072 INDIA Ph: (022) 28471395 Laboratory: Gat#142, Betegaon, Boisar Chilhar Road, Opp. Union Park, Boisar (E) Tal-Palghar, Dist Palghar-401501, INDIA Phone (02525) 284881/931



Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021

	IEC 60529:2013		
Clause	Requirement – Test	Result-Remark	Verdict

13	Tests for protection against so First characteristic numeral.	olid foreign	objects indicated by th	e	
First,	Test means (object probes	Test	Test Conditions		N
characteristic	and dust chamber)	force	Refer IEC		
Numeral.			60529:2013		
0	No test required	_	_		N
1	Rigid sphere without handle	50N	Cls.13.2		N
	or guard 50 mm diameter.	±10%	01 10 0		
2	Rigid sphere without or	30N	Cls.13.2		N
	guard 12, 5 mm diameter.	±10%	SI 10.0		
3	Rigid steel rod 2,5mm	3N±	Cls.13.2		N
	diameter with edges free	10%			
	from burrs		01 10 0		
4	Rigid steel wire 1, mm	1N±	Cls.13.2		N
	diameter with edges free	10%			
	from burrs.				NT.
5	Dust chamber, with under	NA	Cls.13.4+13.5		N
	pressure				
6	Dust chamber, The	NA	Cls.13.4+13.6	For 8 Hrs, As	P
	enclosure is maintained		0	extraction rate is	
	below the			less than 40	
	Surrounding atmospheric			volumes per hour	
	pressure by a vacuum pump.			and max	
				depression of 20	
				mbar.	
13.6.2	Acceptance conditions for the			Before dust test.	Р
	The protection is satisfactory i	f no hazard	ous deposit of dust is	(i) IR test was	
	observable inside the UUT at t	he end of te	est.	conducted	
				between all	
				terminals are	
				shorted together	
				and the body of	
				UUT, applied	
				voltage 500 V.d.c	
				for 1 minute.	
				Observation: IR	
				observed >10GΩ.	
				Before dust test.	
				(ii) HV test was	
				conducted	
				between all	1
				terminals are	163
				shorted together	113/
				and the body of	IIEL.



Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021

working for a safer tommorow UUT, applied voltage 2KV a.c for 1 minute. Observation: No flash occurred. After dust test, (i) No ingress of powder found inside the UUT. (ii) IR test was conducted between all terminals are shorted together and the body of UUT, applied voltage 500 V.d.c for 1 minute. Observation: IR observed >10G $\Omega$ . (iii) HV test was conducted between all terminals are shorted together and the body of UUT, applied voltage 2KV a.c for 1 minute. Observation: No flash occurred.





Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021

	IEC 60529:2013		
Clause	Requirement – Test	Result-Remark	Verdict

14	Tests for protection against water indica numeral.	ited by the second	cnaracteristic	
Second,	Test means	Test Conditions		N
characteristic		Refer IEC		
Numeral.		60529:2013		
0	No test required	Cls.14.2.0		N
1	Drip box, Enclosure on turntable	Cls.14.2.1		N
2	Drip box, Enclosure in 4 fixed positions of 15 ° tilt	Cls.14.2.2	*	N
3	oscillating tube or spray nozzle, 60° from vertical	Cls.14.2.3		N 
4	oscillating tube or spray nozzle, 180° from vertical	Cls.14.2.4		N
5	6.3-mm nozzle, tested with a spraying nozzle, distance 2.5 m to 3 m, water flow rate 12.5 l/min	Cls.14.2.5		N
6	12.5-mm nozzle, tested with a spraying nozzle, distance 2.5 m to 3 m, water flow rate 100 l/min	Cls.14.2.6		N
7	Immersion tank, Temporary immersion in water in service position, Water temperature does not differ from that of equipment by more than 5K.	Cls.14.2.7		N
8	Immersion tank, Continuous immersion subject to agreement. Water temperature does not differ from that of equipment by more than 5K. Test Duration: 48 Hour.	Cls.14.2.8	Immersion depth: The UUT is located 3 meter below the surface of water.	P
-	Acceptance conditions for IPX8: The protection is satisfactory if no water has accumulated near the insulation, cable end or entered cables or interferes with the correct operation of the equipment.	Cls.14.3	Before dust test. (i) IR test was conducted between all terminals are shorted together and the body of UUT, applied voltage 500 V.d.c for 1 minute. Observation: IR observed >10GΩ. Before dust test. (ii) HV test was	P



Report No.: KLPL/BTG/20/12-102

Date: 21.01.2021

a safer tommorow			
		between all	
		terminals are	
		shorted together	
		and the body of	
		UUT, applied	
		voltage 2KV a.c	
		for 1 minute.	
		Observation: No	
		flash occurred.	
		After dust test,	
		(iv) No ingress of	
		powder found	
		inside the UUT.	
		(v) IR test was	
		conducted	
		between all	
		terminals are	
		shorted together	
		and the body of	
		UUT, applied	
		voltage 500 V.d.c	
		for 1 minute.	
		Observation: IR	
		observed >10G $\Omega$ .	
		(vi) HV test was	
		conducted	a j
		between all	
·		terminals are	
		shorted together	
		and the body of	
		UUT, applied	
		voltage 2KV a.c	
		for 1 minute.	
		Observation: No	
		flash occurred.	
- Tests for protection against access to	Cls.15		N
hazardous parts indicated by the			
additional letter.			

# SUMMARY OF INGRESS PROTECTION TESTS ACCORDING TO IEC 60529:2013 Conclusion of the IP68 test: PASS.

The results of the tests were in compliance with the requirements in the standard IEC 60529:2013 UUT=Unit Under Test



Website: www.karandikarlab.com



Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021



Picture1: Centork Q650 3 Phase



Pictute2: No ingress of powder & water observed



Head Office: B-101, Ansa Industrial Estate, Saki Vihar Road, Saki Naka, Andheri (E) Mumbai-400072 INDIA Ph: (022) 28471395 Laboratory: Gat#142, Betegaon, Boisar Chilhar Road, Opp. Union Park, Boisar (E) Tal-Palghar, Dist Palghar-401501, INDIA Phone (02525) 284881/931



Report No.: KLPL/BTG/20/12-102 Date: 21.01.2021



Pictute3: No ingress of powder & water observed

**END OF REPORT** 



